



No.589-592,Bo Aung Kyaw Street,Yangon-Pathein High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar

Print Date : 27-May-2025

Taxi (Bus, Motorcycle, 3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2023-05-16	Concrete Equipment	Service	Naing Lin Htan(3)	NPT Trip	18:30	Aung Min Galar	Thamine Moditar Housing	20,000	20,000	GA Manager Approved	

Hning

Hnin Thant^U Oo

Zarni Aung



TRAVELLING REPORT

Date: 28.5.25

Report To		
Employee Name	Ncing Lim Htun	
Position	mechanic	
Department	Service	
Business	CE-3	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	23.4.25 (8:00 AM)	16.5.2025 (7:00 PM)
Total Days		
Trip Information	1. From <u>APT</u> To <u>Ygn</u>	
	2. From _____ To _____	
	3. From _____ To _____	
Purpose For Travelling	D&C (719) / Traveling repair the hydraulic function slow (559)	
Travel Date	Activities	Remark
23.4.2025	<p>Go to Job site.</p> <p>We inspected the machine.</p> <ul style="list-style-type: none"> - And, checked cobland, engine oil, hydraulic oil, final drive oil, and swing oil - Fan belt, Air-con. system, wiper, light bulb, radio, APPM, hydraulic & engine system leakage. - All are ok. 	D&C (719) CC Pol Htun.

Reported by
 Sign : Ncing Lim Htun
 Name : Ncing Lim Htun
 Position : Mechanic

Checked by
 Sign : [Signature]
 Name : Heir Itika Soe
 Position : J-H

(DH/AGM/GM)

Approved by
 Sign :
 Name :
 Position :

(COO)

05-CHL-HRM-FRM-064-01

Travel Date	Activites	Remark
24.4.2025	Go to Job site. with customer	(SSQ) U Tin Myo Lin
25.4.2025	<ul style="list-style-type: none"> - We inspection the machine. - And then, we checked the performance task. All are ok. - But, after 2 hour working all junction slow. - So, we adjust regulator but not ok. 	hydraulic. (08 to 40)
26.4.2025	<ul style="list-style-type: none"> - We request the old good. regulators to yangon. 	
27.4.2025	<ul style="list-style-type: none"> - Waiting part. 	
28.4.2025	<ul style="list-style-type: none"> - We drain the hydraulic. And, dismounted the regulator. - Cleaning the main pump. - mounted the old good. regulator - Filled. the hydraulic - Test run the machine - Priming, chain junction slow. 	

Travel Date	Activites	Remark
29.4.2025	<ul style="list-style-type: none"> - Dam port-relief valve dismantled & clean. - mounted the port-relief valve. - Performance test run. All are ok. 	
30.4.2025	<ul style="list-style-type: none"> - We checked the chain junction. - examine joint leakage. 	
1.5.2025	<ul style="list-style-type: none"> - We checked RCV leakage. - And, we change the pusher seal. - But, not ok. - We request the (new pusher & regulator) to yangon 	
2.5.2025	<ul style="list-style-type: none"> - Monitoring & waiting part. 	<p>(အပူပေးစနစ်အတွက် အပူပေးစနစ်ကို စစ်ဆေးပြီး အပူပေးစနစ်ကို ပြန်လည်ချိတ်ဆက်ပါ။)</p>
3.5.2025	<ul style="list-style-type: none"> - monitoring & waiting part 	
4.5.2025	<ul style="list-style-type: none"> - monitoring & waiting part (not connection) 	

Travel Date	Activites	Remark
5.5.2025	Monitoring & waiting part.	
6.5.2025	- weather condition is not good.	
7.5.2025	- weather condition is not good.	
8.5.2025	- Regulator & pusher reach the bottom of the maintain site.	
	- But, the road conditions can be taken because of bad.	
9.5.2025.	- Weather condition & the road conditions is not good.	
10.5.2025	- Regulator & pusher reach to machine.	
	- Drain the hydraulic	
11.5.2025	- Dismantled the regulator	
	- mounted the regulator (new)	
	- Removed the RCV pusher	
	- Change new pusher.	
	- Test run the machine.	

Travel Date	Activities	Remark
12.5.2025	<ul style="list-style-type: none"> - Test run the machine - Bud chain junction slow - need to repair center joint seal/leakage 	
13.5.2025	<ul style="list-style-type: none"> - Discuss with customer - Told to repair the travel junction at reach (emergency) - All are ok. Job was finished. 	
14.5.2025	<ul style="list-style-type: none"> - Weather condition is not good. 	
15.5.2025	<ul style="list-style-type: none"> - Job site to WPT. 	
16.5.2025	<ul style="list-style-type: none"> - WPT to YAN. 	

Sayar U Aye Min Htun Dear Sayar and Ko Aung Hein Win.

Trip အတွက် Approved ဝယ်ငွေတင်ကြိုလွှဲပေးရန်

သူတို့ဆောင်ရွက်ပေးမည့် - Naing Lin Htun

ရာထူး - Senior Mechanic

မှား - CE3+CNC BU

၂ယောက်ခန့်ပို့ဆောင်ပေးရမည် - (1) person

၃) ဝယ်ငွေပေးမည့်နေရာ - Nay Pyi Taw, Tatkon & Melkita, Yarmethin

Customer - U Paw Htun & U Tin Myo Lin

၄) ဝယ်ငွေပေးမည့်အကြောင်းအရာ - ME210(719) Regular Service and MCV repair (559)

၅) ဝယ်ငွေပေးရမည့်နေ့ရက် (23.4.2025) နှင့် ပြန်ပေးရမည့်နေ့ရက် (28.4.2025) ဝန်ဆောင်ပေးရန်

(6) Transportation - Car Tickets (အပြန်အဝှောက်)

Customer - U Paw Htun & U Tin Myo Lin

Model - ME210 (719+559)

Trip အတွက် Approve ခံယူပေးရန် လိုအပ်ပါသည်

edited 2:38 PM



Bo Bo

Bo Bo

YE` MIN KYAW @HTHS1 @GxVictor...

၆၁၁၆၁၁၁၁၁၁: ၆၆၁၁၁၁၁၁၁: 11:30 AM

Sayar U Aye Min Htoon

Thet Phyo Aung

Sayar U Aye Min Htoon Dear Sayar and Ko Aung Hein Win. Trip ၁၁...

Please proceed to go to NPT customer U Paw Htun and U Tin Myo Lin.



1:05 PM



BR's Service Report
89.4 KB



Ma Win Zar Hlaing

last seen at 2:34 PM



Dear MD,

(၁) အမည်- Naing Lin Htun,

ရာထူး - Mechanic

ဌာန - CE3+CNC BU

(၂) သွားရောက်သည့် ဝန်ထမ်း အရေအတွက် -
1 ယောက်

(၃) ခရီးသွားသည့်နေရာ - Nay pyi law,
Tatkon & Meiktila, Yamethin

(၄) ခရီးသွားသည့် အကြောင်းအရာ -
Machine ME210(719) Regular service
and MCV repair

(၅) စတင်သွားရောက်မည့် နေ့ရက် -
24.4.2025

ခန့်မှန်းခြေ 1 Week ခန့်ကြာနိုင်ပါသည်။

NPTရုံးတွင်တည်းပါမည်။ Car tickets နှင့်
သွားပါမည်။

Trip Approved အတွက် တောင်းခံအပ်
ပါသည်ရှင့် 

11:32 AM ✓✓

Message





Ma Win Zar Hlaining
last seen at 2:34 PM



Thiri Mon

ဟုတ်မ ပိတ်ရက်ကတည်းက MDY ကယ်ဆယ်ရေး...
ညီမလေး သွားမီးမီးဆီ မှတ်ချက်နဲ့ပဲရေးလိုက်
တော့နေနော်

11:56 AM

MD Approved ပေးမှာတော့ မဟုတ်တော့ဘူး

11:56 AM

သွားငြိတာမဟုတ်ဘူးမ ရှုက NPT နှာပိတ်ရက်
နေလို့ job ပေါ် လာတာနဲ့သွားခိုင်းလိုက်တာမ
မှတ်ချက်နဲ့ဆီ ရတယ်လားမ

11:58 AM

ရှုက သွားနေပီလား

12:03 PM

ဒီနေ့မှ သွားမှာလား

12:03 PM

ဟုတ်မ job သွားနေပါပြီ
❤️ 🌸

12:04 PM

မှတ်ချက်နဲ့ပဲသွားလိုက်တော့နေနော်

12:04 PM

System approved တော့ပေးလိုက်ပါမယ်
ညီမလေး

12:05 PM

နောက်မသွားခင်ကြိုတောင်းပေးပါနေနော်

12:05 PM

Message






12:30 PM | 89.8KB/s



ပျာကြီး

last seen at 10:27 AM

49% 11:15



Forwarded from

Naing Lin Htin

Hello တွဲအောင်ဖြိုးလင်းခင်ဗျာ

NPTကိုcustomer U Paw Htin &U Tin
Myo Linn စာအတွက်(23.4.2025)to
(16.5.2025)ရက်နေ့ထိရှုံးကြောင်း BOH
Approve လေးတောင်းချင်လို့ပါ 9:59 AM

Please, proceed by policy. 8:28 PM

Message








CE3+CNC Service Team
to members

Pinned message

- Starter motor - Battery 2pcs - Engine oil sensor - Crank sensor - Cam sensor - E...





Shot on Y50
 AI Quad camera